

**JIUYUM FOAM  
JENNY TECH**

# PROCESS OF PRODUCTION

# 1 RAW MATERIAL WAREHOUSE

## Key Points:


- 1、 check color in lamphouse VS signed fabric
- 2、 check fabric weight
- 3、 Fabric on Checking Machine for the width/design/defects, etc
- 4、 Keep first-in first-out Regular



# 2 CUTTING WORKSHOP

## Key Points:

- 1、Signed first-cutting
- 2、Remark dyelot Number with assortment
- 3、Metal Control



裁剪工序巡检报告					
日期	班次	检查人	检查项目	检查结果	备注
2023-10-10	1	张三	首件检查	合格	
2023-10-10	1	张三	首件检查	合格	
2023-10-10	1	张三	首件检查	合格	
2023-10-10	1	张三	首件检查	合格	
2023-10-10	1	张三	首件检查	合格	
2023-10-10	1	张三	首件检查	合格	
2023-10-10	1	张三	首件检查	合格	
2023-10-10	1	张三	首件检查	合格	
2023-10-10	1	张三	首件检查	合格	
2023-10-10	1	张三	首件检查	合格	





# 4 FILLING WORKSHOP

## Key Points:

- 1、Foam Recovery Testing
- 2、Filling Weight
- 3、100% Metal Detection



# 5 ASSEMBLY WORKSHOP

## Key Points:

- 1、 100% Inspection under standard
- 2、 Arrange Products Mid-Testing



# 6 PACKING

## Key Points:

- 1、 100% Metal Detection after standing 24 hours vacuum packed
- 2、 Red bins for defect product



# TESTING LAB

- Appearance after home laundering
- Colorfastness to crocking-wet/dry
- Foam recovery testing after vacuum
- Weight checking
- Color checking



# FACTORY FOAM TESTING

## Key Points:

- 1、 Machine check for Filling recovery
- 2、 Foam testing for surface hardness/tensile strength/compression permanent deformation
- 3、 Foam production sample testing and testing sample kept for half a year

